

メーカー	サイズ(型)	型式	ネジ穴寸法				
			W	H	YK-PL002	YK-PL005	YK-PL006
日立	50	L50-N1	200	400	○	○	○
		P50-GP08	400	330	○	○	○
		P50-XP03	400	330	○	○	○
		P50-XP035	400	330	○	○	○
		P50-XP05	400	330	○	○	○
		P50-XP07	400	330	○	○	○
		P50-XR02	400		○	○	○
		PMT-5030XG	400	330	○	○	○
		PMT-5040XG	400	330	○	○	○
	47	L47-GP1	300	300	○	○	○
		UT47-BX700J	500	200	○	×	○
		UT47-XP770B/W	500	200	○	×	○
		UT47-XP800B/W	500	200	○	×	○
		UT47-XV700	500	200	○	×	○
	46	P46-GP08	400	230	○	○	○
		P46-XP03	400	330	○	○	○
		P46-XP035	400	330	○	○	○
		P46-XP05	400	330	○	○	○
		P46-XP07	400	230	○	○	○
	42	L42-GP1	300	300	○	○	○
		L42-XP03	200	200	○	○	○
		L42-XP035	200	200	○	○	○
		L42-XP05	200	200	○	○	○
		L42-XP07	300	300	○	○	○
		L42-XP08	300	300	○	○	○
		L42-ZP05	200	200	○	○	○
		P42-HP03			×	×	×
		P42-HP05	400	330	○	○	○
		P42-GP08	400	230	○	○	○
		P42-XP03	400	330	○	○	○
		P42-XP035	400	330	○	○	○
		P42-XP05	400	330	○	○	○
		P42-XP07	400	230	○	○	○
		P42-XP700CS	400	230	○	○	○
		PMT-4230G	400	330	○	○	○
		PMT-4240G	400	230	○	○	○
		UT42-BX700J	500	200	○	×	○
		UT42-XP770B/W	500	200	○	×	○
		UT42-XP800B/W	500	200	○	×	○
		UT42-XV700	500	200	○	×	○
	39	L39-N1	200	100	×	×	-
	37	L37-H07	400	200	○	○	-
		L37-XP03	200	200	○	○	-
		L37-XP035	200	200	○	○	-
		L37-XP05	200	200	○	○	-
		L37-XP07	200	200	○	○	-
		L37-XP700CS	200	200	○	○	-
		L37-XP08	200	200	○	○	-
		L37-XP800CS	200	200	○	○	-
		L37-ZP05	200	200	○	○	-
UT37-BX700J		400	200	○	○	-	
UT37-XP770B/W		400	200	○	○	-	
UT37-XP800B/W		400	200	○	○	-	
UT37-XV700		400	200	○	○	-	
L32-H07		400	200	○	○	-	
L32-HP07		400	200	○	○	-	
L32-HR01		630		○	×	-	
L32-HR100CS		630		○	×	-	
L32-K1		200	200	○	○	-	
L32-WP03		200	200	○	○	-	
L32-XP05		200	200	○	○	-	
L32-XP07		200	200	○	○	-	
L32-XP700CS	200	200	○	○	-		
L32-XP08	200	200	○	○	-		

メーカー	サイズ(型)	型式	ネジ穴寸法			YK-PL002	YK-PL005	YK-PL006
			W	H				
日立		L32-XP800CS	200	200	○	○	-	
		UT32-BH700JB/W/R/A	400	200	○	○	-	
		UT32-BX700JB/W/R/A	400	200	○	○	-	
		UT32-HV700/B/R/A	400	200	○	○	-	
		UT32-XP770B・W	400	200	○	○	-	
		UT32-XP800B/W	400	200	○	○	-	
	42	CMP4221J	414	308	○	○	-	
		CMP4221JS	414	308	○	○	-	

の機種は壁掛け対応にする為に純正アタッチメントが必要